

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>BF25-35</b> MRF137 1 MOTA MRF171 1 MOTA	<b>BF164</b> (Cont'd) BF198 1 PHIN	<b>BF198</b> 2N5201 3 MOTA BC107 3 SGSI	<b>BF245A</b> (Cont'd) 2N5458 3 INL 2N5484 3 INL	<b>BF247</b> (Cont'd) TMPF4091 3 SPR TP4091 3 SPR	<b>BF257</b> (Cont'd) 40408 3 RCA BD115 3 PHIN	
<b>BF50-35</b> MRF172 1 MOTA	<b>BF165</b> BF185 1 PHIN BF495 1 PHIN	BC547A 3 PHIN BC548A 3 PHIN BF196 3 PHIN	2N5951 3 IFC 2N5953 3 IFC DE451 3 DGE	<b>BF247A</b> 2N4091 1 INL DE466 3 DGE	BSW66 3 PHIN BSW67 3 PHIN BSW68 3 PHIN	
<b>BF100-35</b> MRF174 1 MOTA	<b>BF166</b> BF200 1 PHIN	THC4286 3 SPR THC4287 3 SPR	DE452 3 DGE DE457 3 DGE PN4304-18 3 NSC	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	D44T1 3 GESY D44T2 3 GESY DE154 3 DGE	
<b>BF108</b> D44T1 1 GESY	<b>BF169</b> BF115 1 PHIN BF494 1 PHIN	<b>BF199</b> MPSH24 1 MOTA SF245 1 MIKG	THJ4304 3 SPR THJ4416 3 SPR THJ5457 3 SPR	<b>BF247B</b> 2N4091 1 INL DE466 3 DGE	MPSA43 3 MOTA	
<b>BF109</b> D40V1 1 GESY	<b>BF174</b> 2N3440 1 RCA BF258 3 SIEG	BF197 3 PHIN	THJ5668 3 SPR TMPF4304 3 SPR TMPF4416 3 SPR	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	<b>BF258</b> BF337 1 PHIN D40V1 1 GESY	
<b>BF111</b> 2N3440 1 RCA BD115 3 PHIN	<b>BF177</b> BF257 1 SGSI BF336 3 PHIN	<b>BF206</b> 2N918 1 PHIN BF799 3 SIEG	DE161 3 DGE PN918 3 NSC TMPF5457 3 SPR	<b>BF247C</b> 2N4091 1 INL DE466 3 DGE	2N3440 3 RCA 2N6515 3 MOTA 40412 3 RCA	
BFN18 3 SIEG BFN26 3 SIEG D44T2 3 GESY	MPSH04 3 MOTA	DE161 3 DGE PN918 3 NSC THC918 3 SPR	TP4304 3 SPR TP4416 3 SPR TP5668 3 SPR	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	BC639 3 PHIN D44T1 3 GESY DE154 3 DGE	
DE396 3 DGE TN3440 3 NSC	<b>BF178</b> 40412 1 RCA BF258 1 SGSI	<b>BF214</b> BF115 1 PHIN BF494 1 PHIN	<b>BF245B</b> 2N4416 1 INL 2N5338 3 MOTA	<b>BF248</b> 2N2221 1 PHIN 2N2222 1 PHIN	2N3440 3 RCA 2N6515 3 MOTA 40412 3 RCA	
<b>BF115</b> 2N2218 3 MOTA BF494 3 PHIN	<b>BF179</b> BF337 3 PHIN BFN18 3 SIEG	BF494 1 PHIN MPSH04 3 MOTA	2N5459 3 INL 2N5485 3 INL 2N5952 3 IFC	GES2222A 3 GESY GES2222 3 GESY PN2221 3 NSC	DE154 3 DGE GES4927 3 GESY THC4927 3 SPR	
BF494 3 GESY D40E1 3 GESY D40E5 3 GESY	<b>BF179A</b> D40V1 1 MOTA SF245 3 MIKG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	DE451 3 DGE DE452 3 DGE DE457 3 DGE	PN2222 3 NSC PN2222 3 NSC THC2221 3 SPR	TP4927 3 SPR	
DE128 3 DGE DE319 3 DGE	<b>BF179B</b> 2N3440 1 RCA BF259 1 SGSI	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	PN4303-18 3 NSC SIX 3 SPR THJ4303 3 SPR	THC2222 3 SPR TMPT2221 3 SPR TMPT2222 3 SPR	<b>BF259</b> BF338 1 PHIN D40V3 1 GESY	
<b>BF118</b> BF338 1 PHIN D40V1 1 GESY	<b>BF179C</b> D40V1 1 MOTA SF245 3 MIKG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5669 3 SPR TMPF4303 3 SPR TMPF4416 3 SPR	TP2221 3 SPR TP2222 3 SPR	2N3439 3 RCA 2N3440 3 RCA BD115 3 PHIN	
2N3440 3 RCA BF259 3 SGSI	<b>BF179D</b> 2N3440 1 RCA BD115 3 PHIN	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	TP5669 3 SPR TMPF5458 3 SPR TMPF5669 3 SPR	<b>BF249</b> 2N2906A 1 PHIN 2N2907 1 SGSI	BD115 3 PHIN MPSA42 3 MOTA	
<b>BF119</b> BF337 1 PHIN 2N3440 3 RCA	<b>BF179E</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	TP4303 3 SPR TP4416 3 SPR TP5669 3 SPR	BSS80C 3 SIEG DE159 3 DGE GES2907 3 GESY	<b>BF260</b> BF200 1 PHIN	
BF258 3 SGSI	<b>BF179F</b> D44T2 3 GESY D44T2 3 GESY	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF245C</b> 2N4416 1 INL 2N5337 3 MOTA	PN2906A 3 SPR PN2907 3 NSC THC2906A 3 SPR	<b>BF261</b> BF196 1 PHIN BF198 1 PHIN	
<b>BF120</b> BC394 1 SGSI	<b>BF179G</b> 2N3440 1 RCA D40V1 1 MOTA	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	2N5484 3 INL 2N5486 3 INL 2N5950 3 IFC	THC2907 3 SPR TMPT2906A 3 SPR TMPT2907 3 SPR	<b>BF268</b> BFY90 1 PHIN SD1300 3 THCS	
<b>BF123</b> BF197 1 PHIN BF199 1 PHIN	<b>BF179H</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	2N5951 3 IFC 2N5953 3 IFC DE451 3 DGE	TP2906A 3 SPR TP2907 3 SPR TPQ2906A 3 SPR	<b>BF272</b> 2N2906 1 PHIN DE159 3 DGE	
MPSH24 3 MOTA SF245 3 MIKG	<b>BF179I</b> D44T2 3 GESY D44T2 3 GESY	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	DE452 3 DGE DE457 3 DGE MPF108 3 MOTA	GES2907 3 GESY PN2906A 3 NSC PN2907 3 NSC	GES2906 3 NSC PN2906 3 NSC TMPT2906 3 SPR	
<b>BF125</b> BF197 1 PHIN BF199 1 PHIN	<b>BF179J</b> 2N3440 1 RCA D40V1 1 MOTA	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	PN4302-18 3 NSC SIX 3 SPR THJ3819 3 SPR	THC2907 3 SPR TMPT2907 3 SPR TP2907 3 SPR	<b>BF273</b> BF241 1 PHIN SF225 3 MIKG	
MPSH24 3 MOTA SF245 3 MIKG	<b>BF179K</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ4416 3 SPR THJ5459 3 SPR THJ5670 3 SPR	TPQ2906A 3 SPR	SF245 3 MIKG	
<b>BF127</b> BF197 1 PHIN BF199 1 PHIN	<b>BF179L</b> D44T2 3 GESY D44T2 3 GESY	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5459 3 SPR THJ5670 3 SPR TMPF3819 3 SPR	<b>BF250</b> 2N2222 1 SGSI BSS81C 3 SIEG	<b>BF291</b> BC107 1 SGSI BCX70G 3 PHIN	
MPSH24 3 MOTA SF245 3 MIKG	<b>BF179M</b> 2N3440 1 RCA D40V1 1 MOTA	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5670 3 SPR TMPF3819 3 SPR TMPF4302 3 SPR	GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR	BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR	
<b>BF131</b> BF182 1 PHIN	<b>BF179N</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ4416 3 SPR THJ5459 3 SPR THJ5670 3 SPR	TP2222 3 NSC TMPT2222 3 SPR TP2222 3 SPR	<b>BF292</b> BF258 1 SGSI BF337 3 PHIN	
<b>BF133</b> BF183 1 PHIN	<b>BF179O</b> D44T2 3 GESY D44T2 3 GESY	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5459 3 SPR THJ5670 3 SPR TMPF5670 3 SPR	<b>BF251</b> BF199 1 PHIN MPSH24 3 MOTA	D40V1 3 GESY	
<b>BF134</b> BF200 1 PHIN	<b>BF179P</b> DE396 3 DGE TN3440 3 NSC	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	TP4416 3 SPR TP5670 3 SPR	SF245 3 MIKG	<b>BF292A</b> D40V1 1 GESY	
<b>BF137</b> 2N3440 1 RCA BF257 1 SGSI	<b>BF179Q</b> 2N3440 1 RCA D40V1 1 MOTA	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF246</b> 2N5485 1 INL 2N5245 3 IFC	<b>BF254</b> MPSH04 1 MOTA	<b>BF292B</b> D40V1 1 GESY	
BD115 3 PHIN BF336 3 PHIN	<b>BF179R</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF292C</b> D40V1 1 GESY	
BFN18 3 SIEG BFN26 3 SIEG D40V1 3 GESY	<b>BF179S</b> D44T2 3 GESY D44T2 3 GESY	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	DE452 3 DGE THJ5486 3 SPR TMPF5486 3 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF293</b> BC107 1 SGSI BCX70G 3 PHIN	
DE396 3 DGE TN3440 3 NSC	<b>BF179T</b> DE396 3 DGE TN3440 3 NSC	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF244A</b> 2N5484 1 INL THJBF244A 1 SPR	<b>BF255</b> MPSH04 1 MOTA	BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR	
<b>BF153</b> BF495 1 PHIN MPSH04 3 MOTA	<b>BF179U</b> BF494 3 PHIN DE161 3 DGE	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	2N5246 3 IFC DE180 3 DGE THJ5484 3 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF294</b> BC257 1 SGSI BD115 1 PHIN	
<b>BF154</b> BF196 1 PHIN BF198 1 PHIN	<b>BF179V</b> 2N2221 3 MOTA BF495 3 PHIN	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5484 3 SPR TMPF5484 3 SPR	<b>BF255</b> MPSH04 1 MOTA	D40V2 1 GESY 2N3440 3 RCA BC177 3 SGSI	
<b>BF155</b> BF180 1 PHIN	<b>BF179W</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>BF255</b> MPSH04 1 MOTA	BC557 3 PHIN D44T1 3 GESY THBC257 3 SPR	
<b>BF156</b> BF257 1 SGSI D40V1 1 GESY	<b>BF179X</b> D44T2 3 GESY D44T2 3 GESY	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF244B</b> 2N5485 1 INL THJBF244B 1 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF297</b> BF257 1 SGSI BF336 1 PHIN	
BF336 3 PHIN	<b>BF179Y</b> DE396 3 DGE TN3440 3 NSC	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	2N5245 3 IFC DE180 3 DGE THJ5484 3 SPR	<b>BF255</b> MPSH04 1 MOTA	MPSA43 1 MOTA 2N3440 3 RCA BC177 3 SGSI	
<b>BF157</b> 2N3440 1 RCA BF257 1 SGSI	<b>BF179Z</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5484 3 SPR TMPF5484 3 SPR	<b>BF255</b> MPSH04 1 MOTA	BC557 3 PHIN D44T1 3 GESY THBC257 3 SPR	
D40V1 1 GESY BD115 3 PHIN	<b>BF180</b> BF115 1 PHIN BF494 1 PHIN	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF244C</b> 2N5486 1 INL THJBF244C 1 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF299</b> 2N6515 1 MOTA BF258 1 SGSI	
BF336 3 PHIN BFN18 3 SIEG BFN26 3 SIEG	<b>BF181</b> MPSH04 3 MOTA SF235 3 MIKG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	2N5247 3 IFC THJ5486 3 SPR TMPF5486 3 SPR	<b>BF255</b> MPSH04 1 MOTA	2N3440 3 RCA BFN16 3 SIEG D40V1 3 GESY	
DE396 3 DGE TN3440 3 NSC	<b>BF182</b> BF494 3 PHIN DE161 3 DGE	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF244D</b> 2N5485 1 INL THJBF244D 1 SPR	<b>BF255</b> MPSH04 1 MOTA	MPSA43C 3 SPR S298TS 3 ALGG TMPTA43 3 SPR	
<b>BF159</b> 2N3440 1 RCA D40V1 1 GESY	<b>BF183</b> BF494 3 PHIN DE161 3 DGE	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	2N5246 3 IFC DE180 3 DGE THJ5484 3 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF299</b> 2N6515 1 MOTA BF258 1 SGSI	
BD115 3 PHIN BF336 3 PHIN	<b>BF184</b> BF494 3 PHIN DE161 3 DGE	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5484 3 SPR TMPF5484 3 SPR	<b>BF255</b> MPSH04 1 MOTA	BF337 3 PHIN D40V1 3 GESY DE287 3 DGE	
BFN18 3 SIEG BFN26 3 SIEG D44T2 3 GESY	<b>BF185</b> 2N2221 3 MOTA BF495 3 PHIN	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF246A</b> 2N5639 1 INL THJBF246A 1 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF299</b> MPSA42 1 MOTA BFN18 3 PHIN	
DE396 3 DGE TN3440 3 NSC	<b>BF186</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	BSV79 3 PHIN THJ5639 3 SPR TIS74 3 IFC	<b>BF255</b> MPSH04 1 MOTA	BFN18 3 PHIN D40V1 3 GESY D40V3 3 GESY	
<b>BF160</b> BF495 1 PHIN MPSH04 3 MOTA	<b>BF187</b> 2N3440 1 RCA BF258 3 SGSI	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5639 3 SPR TMPF5639 3 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF299</b> BF259 1 SGSI MPSA42 1 MOTA	
<b>BF161</b> BF183 1 PHIN	<b>BF188</b> BF115 1 PHIN BF494 1 PHIN	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF246B</b> 2N5638 1 INL THJBF246B 1 SPR	<b>BF255</b> MPSH04 1 MOTA	2N3440 3 RCA BFN16 3 SIEG D40V1 3 GESY	
<b>BF162</b> BF200 1 PHIN	<b>BF189</b> BFN18 3 SIEG BFN26 3 SIEG	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	BSV78 3 PHIN THJ5638 3 SPR TIS73 3 IFC	<b>BF255</b> MPSH04 1 MOTA	MPSA43C 3 SPR S298TS 3 ALGG TMPTA43 3 SPR	
<b>BF163</b> BF196 1 PHIN BF198 1 PHIN	<b>BF190</b> D44T2 3 GESY D44T2 3 GESY	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	THJ5638 3 SPR TMPF5638 3 SPR	<b>BF255</b> MPSH04 1 MOTA	<b>BF299</b> BF259 1 SGSI MPSA42 1 MOTA	
<b>BF164</b> BF196 1 PHIN	<b>BF191</b> BF196 1 PHIN BF198 1 PHIN	<b>BF215</b> BF115 1 PHIN BF494 1 PHIN	<b>BF247</b> 2N4091 1 INL DE466 3 DGE	<b>BF255</b> MPSH04 1 MOTA	BFN18 3 PHIN D40V3 3 GESY	